A sa/o 10YR 3/2

B sa/o 2.5Y 6/6

35 C lo sa/sa/o 2.5Y 5/4

usa/o @ 135°

o OW

155-10A

A sa/o 10YR 3/2

B sa/o 2.5Y 6/6

45'C sa/o / lo sa 2.5Y 5/4

usa/ @ 145'

W @ 168 (14')

10 2:09 6 3'al

DOH 55-115
in cente

0-10' (120) +

Perc 6" 7m/in

DOH 65-10-D

0-6 A sa/o 10YR 5/2

6-24 B sa/o 10YR 6/6

24-168C loam to sa/o 2.5Y 5/4

GW @ 168

MP 55-4 - 4/21/21

236 - (18+4) = 214 Dy
to saw

DOH 65-10 E

0-10 A sa/o 10YR 5/2

10-21 B sa/o 2.5Y 6/6

21-96 C loam to sa/o 2.5Y 6/4

Refusal @ 96"

NO GW / Wetness

NOTE

Soil is consistent + this will allow DOH's to be considered per Title 5

4/21/21 Reviewed GS for area of testing to abutter's shed & Drains to main property SHS towards 25 Farm

ES±

Flood fo	
Top of grade, ft	14.09
Aquafer depth, ft	00
nductivity, ft/day	

Lot 3 Farm Rd 11/9/21
PM
Deshong Wang PE
Murchison- DWQE/RSE

DOH 5-2

0-4 A sa/l 10YR 5/2
4-30 B sa/l 10YR 6/6
30-180+ C l/sa 2.5Y 5/4

NO Rafusa/
NO GN

NOTE Many surface boulders Sa DOH 5-2 & perc pad 5-2

Perc 5-2

(48-64

Sat 3:25
12-3:40
11-3:44
10-3:49
9-3:54
8-3:59
7-4:04
6 4:09

5 ml/10

5-2

US Soil Web

Hollis - 35%
Rock Outcrop 30%
Charlton 20%
Canton 10%
Montauk 3%

55 Farm

Monitor Pipes

4/2/21

MP	T-B	T-6W	T-6
55-2	215	—	? 18
55-5	176	136	? 20
55-5-B	149	83	24
55-5A	139	114	16
55-5C	159	138	16
55-4	235	—	22
55-3	255		33
65-10C	177	—	26
65-10-D	174		6
65-10	153	140	22
65-10-B		139	6
65-10A	200	150	24

MP
55-2

55-2

Drive

55-5A

55-3

55-5C

M.P.

MP
55-4
Checked
4/21/21

Perc 55-2

Sat 2:43 @ 4054

65 Farm Road

01-20-21
PM

Robert Murchison, Owner Dashing Wang PE
& Francis
Engineer Note "Ground Morraine" John, Mardonald Bros

DOH 65-10A

0-24 A sa/o loame 3/2
24-30 B sa/o 5/6
30-150 C sa/o to losa
Pockets of rotted ledge Northside
GW Weep Start @ 144" GW @ 120

Perc 65-10A

Sat-3:47 C 48-60
12-4:02 9-4:08
11-4:04 8-4:11
~~10-4:06~~ 7-4:15
4 m/in 6 4:19

MP 6510A

146 - 24 = 122"

GW @ 126'

MP 65-10
GW @ 138 - 22 = 116'

MP -65-10-C
Dry @ 176 - 26 = 150 NO GW

x Well across street to be surveyed to determine if base downhill

US Southwest - Hollis Rock Quarry
Chaffee Complex

4/27/21 Monitoring

MP	T-B	T-GW	T-G	GW @
11A New	238	232	43	189 GW
5-11	211	-	24	187 NO GW
5-10A New	180	-	24	156 NO GW
-10	172	-	37	135 NO GW

Lot 3 Farm

Cool Cloudy

11/10/21

Dechong Wang PE & SE

Bob Murchison Owner

DOH 5-1

0-9 A sa/o 10 4/2 3/2

9-36 B sa/o 2.5Y 6/6

36-168 C co med lo sa 2.5Y 5/4

NO GW

NO Mottles

See USSoil Web on past pg~

Perc 5-3

sht 11:04

12 - 11:20

11 - 11:22

10 - 11:25

42-60

9 - 11:28

8 - 11:31

7 - 11:33

6 - 11:35

3 m/in

DOH 5-3

0-4 A sa/o

4-30 B sa/o to 2.5Y 6/6

30-54 C1 sa me 2.5Y 6/4

54-180 C2 co me lo sa 2.5Y 5/4

NO GW / NO mottles



55 Farm Road | 04.26.21

Back of House













MP 55-11

209-24 = 185 Dry

MP 55-10A

149-27 = Dry @ 121

MP 55-11A

147-21 = Dry @ 126

MP 55-10

172-37 = Dry @ 135'